ANALOG PT100-TRANSMITTER





T03BU/WE

Analog Pt100-transmitter (transmitter 0 ... 10 V, set by our works)

General:

These transmitter are designed for industrial applications and are used to measure the temperature through Pt100 resistance thermometers in 2-/3-wire circuits connections. The 0 ... 10 V output signal is linear with temperature. The advantages of a continuous analog signal path and those of digital adjustment have been combined in the realization of this transmitter series.

analog signal path and those of digital adjustment have been combined in the realization of this transmitter series.		
Specifications:		
Measurement input:	Pt100 (DIN EN60751)	
Measuring range:	-200 +850 °C	
Measuring span:	40 1050 K	
Zero shift:	at span <75 K: -40, -20, 0, +20 or +40 °C at span =75 K: ±50 °C at span >75 K: ±(span * 0.2 + 35 °C)	
Sensor connection:	2- or 3-wire connection	
Measuring current:	<0.5 mA	
Max. perm. line resistance (3-wire):	11 Ohm per conductor	
Sampling time:	continuous because of analog signal path	
Output signal:	0 10 Volt, 3-wire technology	
Setting time on a temperature change:	≤10 ms	
Transfer characteristic:	linear with temperature	
Transfer accuracy:	±0.2 % FS	
Calibration accuracy:	$\leq \pm 0.2$ °C or ± 0.2 % of measuring span	
Supply voltage: U _B	15 30 V DC	
Supply voltage error:	±0.01 % FS / V	
Permissible load R _L :	R _L ≥10 kOhm	
Load error:	≤ ±0.1 % FS	
Operating temperature:	-40 +85 °C	
Relative humidity:	0 95 % RH (non condensing)	
Storage temperature:	-40 +100 °C	
Electric connection:	via terminals, cross section of connection terminals max. 1.75 mm ²	
Housing:	PC-housing, suitable for installation in connection head acc.	

to DIN 43729 form B.

Ø 44 mm x 21 mm

Housing: IP54, connection terminals: IP00

unrestricted

approx. 45 g

Accessories and spare parts:

Hutschienenadapter

Operating position:

Protection rating: Weight:

Dimensions:

Art. no. 603659

Hat rail adapter for snap-on the T03 BU to top-hat rail

T03BU/WE - 1 - 2

Greisinger		
Sensor co	nnection	
P2	Pt100 (2-wire)	
P3	Pt100 (3-wire)	
Measurin	g range	
MBS	-20 +20 °C	
MBS	20 60 °C	
MBS	30 60 °C	
MBS	-50 +50 °C	
MBS	-40 +100 °C	
MBS	0 100 ℃	
MBS	-10 +110 °C	
MBS	0 120 ℃	
MBS	0 180 ℃	
MBS	0 200 °C	
MBS	-50 +100 °C	
MBS	-50 +200 °C	
MBS	50 250 °C	
MBS	0 250 °C	
MBS	0 300 °C	
MBS	0 600 °C	
MBS	-200 +850 °C	