

OPTIONAL ACCESSORIES

20



**GSF 40TF (67 cm)**

Item No. 601319

Material moisture insertion probe, with temperature sensor for measurement in pressed bales at a depth of 60 cm, incl. 1 m connection cable.  
Suitable for: pressed hay and straw bales, grain

21



**GTF 38**

Item No. 601347

Material moisture temperature sensor Ø 2.2 mm, for insertion in measuring pole holes, potential-free, recommended for wood moisture measurement

22



**GES 38**

Item No. 601350

Insertion sensor, Type K, potential-free, Ø 4 x 150 mm, 1 m cable (recommended for wood moisture measurement)

23



**GPAD 38**

Item No. 601328

Test adapter (with 2 test points) for GMH 38xx and GMR 110

24



Fig.: GMH3831 in ST-RN

**GKK 3500**

Item No. 601052

Soft case with cutout e.g. 2x GMH 3000 or 5000, 395 x 295 x 106 mm (W x H x D) (devices and accessories not included)

25



**ST-RN**

Item No. 601074

GMH 3000 protective bag made of Nappa leather, 2 connections (1 x round, 1 x rectangular) (suitable for GMH 3831, GMH 3851)